

Agusta A109 Series Helicopters

---

**AD/A109/27**

**Tail Rotor Blades P/N 109-8132-01-107**

**7/97  
DM**

Applicability: Model A109C with tail rotor blades Part Number 109-8132-01-107 with Serial Numbers prefixed A5- installed.

Requirement: Action in accordance with Agusta Bullettino Technico 109-105.

*Note: RAI AD 97-090 refers.*

Compliance: Within 25 hours time in Service after 12 May 1997.

This Airworthiness Directive becomes effective on 12 May 1997.

Background: This Directive is raised to inspect the bonding of the tail rotor blades tip fairing for voids and disbonding. Loss of a tip fairing will cause severe vibration, and may cause severe structural damage that may result in loss of control.