

Eurocopter AS 355 (Twin Ecureuil) Series Helicopters

AD/AS 355/5 **Upper Fin Attachment Fitting - Inspection** **10/82**

Applicability: All model AS 355 not modified in accordance with AMS 350A07.1047 (SB No. 55.02).

Requirement: Action in accordance with Aerospatiale SB No. 05.03.

Note: Bureau Veritas AD 82-99-6(B) refers.

Compliance: Within 10 hours time in service after 1 September 1982 and thereafter at intervals not exceeding 10 hours time in service.

Background: Modification in accordance with SB 55.02 provides terminating action for the mandatory repeat inspection.