

Eurocopter AS 355 (Twin Ecureuil) Series Helicopters

AD/AS 355/45

Cyclic Pitch Change Rod

11/94

Applicability: Models E, F, F1, F2 and N fitted with cyclic pitch change control rod P/No 704A34-113-279, and not fitted with an auto-pilot.

Requirement: Action in accordance with Eurocopter AS 355 Service Bulletin 01-38.

Note: DGAC AD 94-179-051(B) refers.

Compliance: Within 100 hours time in service after 13 October 1994.

Background: The manufacturer has determined that some control rods may not be 'in safety'.