
AIRWORTHINESS DIRECTIVE

On the effective date specified below, and for the reasons set out in the background section, the CASA delegate whose signature appears below revokes Airworthiness Directive AD/B-2/5.

Brantly B-2 Series Helicopters

AD/B-2/5

Tail Cone Reinforcement

6/2009

Requirement: CANCELLED.

This AD is cancelled on 4 June 2009.

Background: This AD, issued in 1960, required modification of the tail cone in accordance with Brantly SB No. 5 to reinforce the structure. The AD compliance was forthwith. As all aircraft would have been modified, the AD is no longer required.



David Villiers
Delegate of the Civil Aviation Safety Authority

17 April 2009