

Brantly B-2 Series Helicopters

AD/B-2/26 Main Rotor Mast Upper Bearing - Replacement 7/67

Applicability: All model B-2, B-2A and B-2B with P/N B2-324 transmission with S/Nos. prior to 307.

Document: Brantly SB No. 21.

Compliance: Within 100 hours time in service after 15 August 1967.