

Brantly B-2 Series Helicopters

**AD/B-2/29
Amdt 1**

**Tail Rotor Drive Shaft - Inspection
and Corrosion Proofing**

12/68

Applicability: All model B2, B2A and B2B.

Document: Brantly SB No. B2B-68-2A.

Compliance: Within 10 hours time in service after 31 December 1968.