

Allison Turbine Engines - 250 Series

AD/AL 250/44
Amdt 1

**Turbine Support and Exhaust
Collector Flow Divider Cracking**

10/86

CANCELLED.

Background: The requirements of this Directive have been cancelled. The inspection procedure, inspection interval and limitations are now contained in the appropriate Operations and Maintenance Manual. The manufacturer advises, CSL 2037/3031 has been cancelled.