

S.L. Industries Commander 100 Series and Volair 10 Series Aeroplanes

---

**AD/AC-100/7**

**Rudder Control System - Inspection  
and Modification**

**8/68**

Applicability: All models with S/Nos. 001 to 250.

Requirement: 1. Remove paint over an area extending 3/4 of an inch aft of the cable attachment hole in the left and right rudder control arms P/N 35321 and inspect for cracking using a 10 power glass.

2. Modify both arms P/N 35321 in accordance with Aero Commander SB No. 1009.

Compliance: Inspect daily until modified. Modify within 100 hours time in service from 1 August 1968.