

S.L. Industries Commander 100 Series and Volair 10 Series Aeroplanes

AD/AC-100/12

Exhaust Muffler - Modification

3/73

Applicability: Models 100 and 100-180 as detailed in the compliance document.

Document: 1. Aero Commander SB 1019; OR
2. FAA AD 73-1-1.

Compliance: Modify within 100 hours time in service after 30 March 1973.