
AIRWORTHINESS DIRECTIVE

On the effective date specified below, and for the reasons set out in the background section, the CASA delegate whose signature appears below revokes Airworthiness Directive AD/AC-SNOW/6.

Ayres Thrush (Snow) Commander Series Aeroplanes

AD/AC-SNOW/6

**Turn and Bank Indicator
Installation - Modification**

9/2008

Requirement: CANCELLED.

This AD is cancelled on 28 August 2008.

Background: This unique Australian AD, raised in 1967 required a modification to ensure the turn and bank indicator was mounted at an angle recommended by the instrument manufacturer.

Compliance was before 1 April 1968.

As all affected aircraft would have been modified by now, this AD is considered to be no longer required.



James Coyne
Delegate of the Civil Aviation Safety Authority

16 July 2008