

---

## AIRWORTHINESS DIRECTIVE

---

On the effective date specified below, and for the reasons set out in the background section, the CASA delegate whose signature appears below revokes Airworthiness Directive AD/AC-SNOW/20.

---

### Ayres Thrush (Snow) Commander Series Aeroplanes

**AD/AC-SNOW/20**

**Aileron Hinge Bracket Bolts**

**9/2008**

Requirement: CANCELLED.

This AD is cancelled on 28 August 2008.

Background: This AD, raised in 1993 against Ayres Corporation Service Bulletin (SB) No. SB-AG-22, required a modification to increase the fatigue life of the lower aileron bracket attachment by replacing the existing attachment bolts with bolts of a larger diameter. Compliance was required within 5 flight hours after 21 June 1993. As all affected aircraft would have been modified by now, this AD is no longer required.



David Villiers  
Delegate of the Civil Aviation Safety Authority

18 July 2008