

Twin Commander (Gulfstream/Rockwell/ Aerocommander 500, 600 and 700) Series Aeroplanes

AD/AC/22

**Induction Air Control Valves and
Mounting Shafts - Replacement**

7/62

Applicability: Model 680F: S/Nos. 871 to 1170.

Document: 1. Aero Commander SB No. 76A; or
2. FAA AD 62-5-1.

Compliance: Forthwith.