

---

## AIRWORTHINESS DIRECTIVE

---

On the effective date specified below, and for the reasons set out in the background section, the CASA delegate whose signature appears below revokes Airworthiness Directive AD/AC/23.

---

### **Twin Commander (Gulfstream/Rockwell/Aerocommander 500, 600 and 700) Series Aeroplanes**

**AD/AC/23**

**Main Landing Gear Struts - Inspection  
and Modification**

**8/2008**

Requirement: CANCELLED.

This AD is cancelled on 31 July 2008.

Background: This unique Australian AD, raised in 1962 against Aero Commander Service Bulletin (SB) No. 80, required an inspection and modification of the main landing gear strut needle bearings to ensure rotation during retraction/extension cycle.

Compliance was forthwith.

As all affected aircraft would have been inspected and modified by now, this AD is considered to be no longer required.



James Coyne  
Delegate of the Civil Aviation Safety Authority

13 June 2008