

Twin Commander (Gulfstream/Rockwell/ Aerocommander 500, 600 and 700) Series Aeroplanes

AD/AC/36 **Wing Front Spar Lower Cap - Inspection** **11/70**
Amdt 2

Applicability: All models 560E, 680 and 680E which do not embody an external or internal spar reinforcement extending to W.S. 127 approved by the Secretary.

Document: Aero Commander SB No. 92.

Compliance: At or before 3000 hours time in service unless already accomplished.