
AIRWORTHINESS DIRECTIVE

On the effective date specified below, and for the reasons set out in the background section, the CASA delegate whose signature appears below revokes Airworthiness Directive AD/AC/70.

Twin Commander (Gulfstream/Rockwell/Aerocommander 500, 600 and 700) Series Aeroplanes

AD/AC/70 Engine Oil Breather Line - Modification 8/2008

Requirement: CANCELLED.

This AD is cancelled on 31 July 2008.

Background: This unique Australian AD, raised in 1979, against Mr. R.P.M. Service Bulletin (SB) No. 004, required a modification to provide an alternative oil breather line outlet should the primary vent become blocked by ice in flight.

Compliance was within 100 hours TIS after 31 August 1979.

As all affected aircraft would have been modified by now, this AD is considered to be no longer required.



James Coyne
Delegate of the Civil Aviation Safety Authority

20 June 2008