

---

## AIRWORTHINESS DIRECTIVE

---

On the effective date specified below, and for the reasons set out in the background section, the CASA delegate whose signature appears below revokes Airworthiness Directive AD/AC/75.

---

### **Twin Commander (Gulfstream/Rockwell/Aerocommander 500, 600 and 700) Series Aeroplanes**

**AD/AC/75                      Main Cabin Door Fasteners - Inspection                      8/2008**

Requirement:    CANCELLED.

This AD is cancelled on 31 July 2008.

Background:    This unique Australian AD, raised in 1981 against Gulfstream American (also known as Aero Commander) Service Bulletin (SB) No. 184, required an inspection to ensure that the main cabin door fasteners had not sheared. Compliance was required within 25 hours TIS after 10 August 1981. As all affected aircraft would have been inspected, and, if necessary, modified long ago, this AD is no longer required.



David Villiers  
Delegate of the Civil Aviation Safety Authority

20 June 2008