

Twin Commander (Gulfstream/Rockwell/ Aerocommander 500, 600 and 700) Series Aeroplanes

AD/AC/89

Aileron Control System

2/95

Requirement: CANCELLED.

Background: AD/AC/89 was issued in response to a USA NTSB recommendation for the FAA to issue an AD requiring a check of the aileron control system.

Subsequently the FAA, after further testing, has determined that the aileron control system meets certification requirements, and that the existing maintenance requirements are adequate.