

Airtractor AT-300, 400 and 500 Series Aeroplanes

AD/AT/6 Amdt 1	Fuselage Fittings - Vertical Fin Front Spar Attachments - Inspection and Modification	11/83
---------------------------	--	--------------

Applicability: All models AT-300, AT-301, AT-302 with S/Nos. 0001 to 0240.

Document: 1. Snow Engineering Co. Service Letter No. 26 and
2. Snow Engineering Co. Service Letter No. 47.

Note: FAA AD 83-18-01 refers.

Compliance: 1. Within 100 hours time in service after 31st July 1983 and thereafter at intervals not exceeding 100 hours time in service.
2. Modification - prior to 2000 hours time in service.

Background: The manufacturer reports that service history indicates cracking of attachment fittings. Amendment 1 of this AD details Snow Engineering Co. Service Letter No. 26 for the repetitive inspection and notes the issue of FAA AD 83-18-01.