

Cessna 150, F150, 152 & F152 Series Aeroplanes

**AD/CESSNA 150/2
Amdt 1**

Main Undercarriage “U” Bolts

11/67

Applicability: All models fitted with “U” bolts P/N 0441161 types.

Requirement: 1. Visual: Inspect the main undercarriage “U” bolts P/N 0441161 in situ for cracks and other damage and check that the “U” bolt retaining nuts are torqued to the values specified in the Cessna Service Manual.

2. Magnetic Particle: Remove the main undercarriage “U” bolts P/N 0441161 and inspect by the magnetic particle method for cracks particularly in the radius of the bends and in the root of the threads.

Compliance: Visual: At intervals not exceeding 100 hours time in service.

Magnetic Particle: At intervals not exceeding 500 hours time in service.