

Cessna 150, F150, 152 & F152 Series Aeroplanes

AD/CESSNA 150/13

Glove Box

11/67

Applicability: All model 150G and 150H.

Requirement: 1. Inspect the forward upper edge of the glove box for adequate clearance from the aileron control chain and sprocket with the control wheel in the elevator full up position.

Note: This inspection may be performed and certified by the pilot.

2. Modify the glove box mountings by bracing to ensure there is no possibility of fouling controls or alternatively remove the glove box.

Compliance: Inspect before further flight. Modify within 5 hours time in service from 23 November 1967.