

Cessna 170, 172, F172, FR172 and 175 Series Aeroplanes

**AD/CESSNA 170/6
Amdt 2**

Undercarriage Attachment Bolts

11/71

Applicability: Model 170, 170A and 170B.

Requirement: Remove the AN7-20A bolts and the nuts attaching the inboard end of the undercarriage spring legs, and replace with new AN7-20A bolts and new nuts.

Compliance: At intervals not exceeding 500 hours time in service. For aircraft which have exceeded 500 hours time in service since last bolt replacement - Within 100 hours time in service after 30 November 1971 and thereafter as above.