

Cessna 185 Series Aeroplanes

AD/CESSNA 185/34

Fuel Cap Alignment Placard

9/80

- Applicability: Model 185 with S/Nos. 632, 185-0001 to 185-1599 and 18501600 to 18503988.
- Requirement: Action in accordance with Cessna SIL No. SE 80-59.
- Compliance: Within 100 hours time in service after 30 September 1980.
- Background: Correct alignment of flush fitting type fuel caps is essential for efficient operation of the fuel tank secondary vent system.