

Cessna 188 (Agwagon) Series Aeroplanes

AD/CESSNA 188/35

Fuel Cap Alignment Placard

9/80

- Applicability: Model A188 (with wing tanks) with S/Nos. 653, 188-0446 to 188-0572, 18800573 and subsequent, Model A188B with S/Nos. 18800967T and subsequent.
- Requirement: Action in accordance with Cessna SIL No. SE 80-59.
- Compliance: Within 100 hours time in service after 30 September 1980.
- Background: Correct alignment of flush fitting type fuel caps is essential for efficient operation of the fuel tank secondary vent system.