

Cessna 205 (210-5) Series Aeroplanes

AD/CESSNA 205/14

Fuel Flow Stabilisation Placard

10/79

Applicability: Model 205 with S/Nos. 205-0001 to 205-0555 (with SK205-5 installed) and 205-0556 to 205-0577.

Requirement: Action in accordance with Cessna SIL No. SE79-25, Supplement No. 1.

Note: FAA AD 79-15-01, Amendment 39-3517 refers.

Compliance: Within 100 hours time in service after 31 October 1979.

Background: The manufacturer has made placards and instructions available to aid in the recognition and elimination of excessive vapour from the aircraft fuel system. In the event of inflight power interruptions engine restart procedures are also detailed.