

Cessna 205 (210-5) Series Aeroplanes

---

**AD/CESSNA 205/15**

**Fuel Cap Alignment Placard**

**9/80**

Applicability: Model 205 with S/Nos. 641 and 205-0001 to 205-0577.

Requirement: Action in accordance with Cessna SIL No. SE 80-59.

Compliance: Within 100 hours time in service after 30 September 1980.

Background: Correct alignment of flush fitting type fuel caps is essential for efficient operation of the fuel tank secondary vent system.