

Cessna 206 Series Aeroplanes

AD/CESSNA 206/41

Rear Wing Spar Doubler

8/85

Applicability: All Model U206 with S/Nos U20601701 to U20604649 (1972 to 1978).

(Normally aspirated and turbocharged models which have had a rear wing spar replaced with one shipped from Cessna Supply Division).

Requirement: Action in accordance with Cessna S.B. SEB85-9.

Compliance: Within 100 hours time in service after 31 August 1985 or at the next scheduled inspection for Maintenance Release issue after 31 August 1985 whichever is the later.

Background: The manufacturer suspects that a quantity of spare rear wing spar assemblies may have been shipped from the Cessna Supply Division without a doubler installed near the attach fitting.