

Cessna 207 Series Aeroplanes

AD/CESSNA 207/24

Fuel Cap Alignment Placard

9/80

Applicability: Models 207 and T207 with S/Nos 20700001 to 20700588.

Requirement: Action in accordance with Cessna SIL No SE 80-59.

Compliance: Within 100 hours time in service after 30 September 1980.

Background: Correct alignment of flush fitting type fuel caps is essential for efficient operation of the fuel tank secondary vent system.