

Emergency Equipment

AD/EMY/15

**Life Jacket Inflation Mechanism P/Nos.
WKA. 36044 and WKA. 35153 - Inspection**

3/81

Applicability: Used on RFD Life jacket Types:

78 Mk 5
50C Mk 3D A.11222-019-6
50C Mk 2E A.11223-019-1
50C Mk 2F A.11224-019-6
50C Mk 5 D.00027-001-1
50C Mk 6 D.00028-001-6
50C Mk 7 D.00029-001-1
72 Mk 2 A.11304-019-1
72 Mk 3 D.00110-001-5
78 Mk 4 A.10668-019-2
78 Mk 6 D.01443-001-3
80 Mk 2 A.07936-019-2
80 Mk 2D P.05500-075-4

Document: The Walter Kidde Company SB 25-109-8082, Issue 2.

Compliance: Before 31 August 1981.

Background: Overseas, in an in-service incident jamming of the gas outlet non-return valve prevented inflation of the life jacket.