



## Airworthiness Directive

**AD No.:** 2019-0216

**Issued:** 02 September 2019

Note: This Airworthiness Directive (AD) is issued by EASA, acting in accordance with Regulation (EU) 2018/1139 on behalf of the European Union, its Member States and of the European third countries that participate in the activities of EASA under Article 129 of that Regulation.

This AD is issued in accordance with Regulation (EU) 748/2012, Part 21.A.3B. In accordance with Regulation (EU) 1321/2014 Annex I, Part M.A.301, the continuing airworthiness of an aircraft shall be ensured by accomplishing any applicable ADs. Consequently, no person may operate an aircraft to which an AD applies, except in accordance with the requirements of that AD, unless otherwise specified by the Agency [Regulation (EU) 1321/2014 Annex I, Part M.A.303] or agreed with the Authority of the State of Registry [Regulation (EU) 2018/1139, Article 71 exemption].

### Design Approval Holder's Name:

AIRBUS

### Type/Model designation(s):

A380 aeroplanes

**Effective Date:** 16 September 2019

**TCDS Number(s):** EASA.A.110

**Foreign AD:** Not applicable

**Supersedure:** This AD supersedes EASA AD 2019-0072 dated 28 March 2019.

## ATA 05 – Time Limits / Maintenance Checks – Airworthiness Limitations Section Part 2 – Damage Tolerant Airworthiness Limitation Items – Implementation

---

### Manufacturer(s):

Airbus

### Applicability:

Airbus A380-841, A380-842 and A380-861 aeroplanes, all manufacturer serial numbers.

### Definitions:

For the purpose of this AD, the following definitions apply:

**The ALS:** Airbus A380 Airworthiness Limitations Section (ALS) Part 2 Revision 08.

**The AMP:** The approved Aircraft Maintenance Programme (AMP) on the basis of which the operator or the owner ensures the continuing airworthiness of each operated aeroplane. For affected A380 aeroplanes registered in Europe, compliance with the approved AMP is required by Commission Regulation (EU) [1321/2014](#), Part M.A.301 paragraph 3.

**New and/or more restrictive tasks:** This includes all tasks that are new and all tasks for which a threshold or interval was reduced, which were introduced into the ALS (as defined in this AD) since the previous ALS Revision that is currently incorporated in the AMP.



**Reason:**

The airworthiness limitations for the Airbus A380 aeroplanes, which are approved by EASA, are currently defined and published in the A380 ALS document(s). The Damage Tolerant (DT) Airworthiness Limitation Items (ALI) are published in ALS Part 2.

Failure to accomplish these instructions could result in an unsafe condition.

Previously, EASA issued AD 2019-0072 to require accomplishment of all DT ALI maintenance tasks as described in ALS Part 2 at Revision 07.

Since that AD was issued, Airbus published the ALS, introducing new and/or more restrictive tasks.

For the reason described above, this AD retains the requirements of EASA AD 2019-0072, which is superseded, and requires accomplishment of the actions specified in the ALS.

**Required Action(s) and Compliance Time(s):**

Required as indicated, unless accomplished previously:

**Maintenance Tasks:**

- (1) From the effective date of this AD, within the thresholds and intervals as defined in the ALS (see Note 1 of this AD), accomplish all maintenance tasks as specified in the ALS, as applicable to aeroplane model and depending on aeroplane configuration.

Note 1: For the purpose of this AD, the thresholds and intervals as defined in the 'Compliance Time' pages of the ALS include specific compliance times for certain tasks.

**Corrective Action(s):**

- (2) In case of finding discrepancies during accomplishment of any task as required by paragraph (1) of this AD, before next flight, accomplish the applicable corrective action(s) in accordance with the applicable Airbus maintenance documentation. If a detected discrepancy cannot be corrected by using existing Airbus instructions, before next flight, contact Airbus for approved instructions and accomplish those instructions accordingly.

**Aircraft Maintenance Programme (AMP) Revision:**

- (3) Within 12 months after the effective date of this AD, revise the approved AMP by incorporating the tasks and associated thresholds and intervals described in the ALS, as applicable to aeroplane model and depending on aeroplane configuration.

**Credit:**

- (4) If, before the effective date of this AD, the AMP has been revised to incorporate the tasks as specified in ALS Part 2 at Revision 07, that action ensures the continued accomplishment of those tasks.

Consequently, for an aeroplane to which that AMP applies, it is acceptable to accomplish the new and/or more restrictive tasks, as applicable to aeroplane model and depending on aeroplane configuration, as defined in, and within the compliance times (see Note 1 of this AD) as specified in, the ALS, to comply with paragraph (1) of this AD.



For that AMP, it is acceptable to incorporate the new and/or more restrictive tasks, as applicable to aeroplane model and depending on aeroplane configuration, as defined in the ALS, into the AMP to comply with paragraph (3) of this AD.

**Recording AD compliance:**

- (5) When the AMP of an aeroplane has been revised as required by paragraph (3) or (4) of this AD, as applicable, that action ensures continued accomplishment of the tasks as required by paragraphs (1) and (2) of this AD for that aeroplane. Consequently, after revising the AMP, as required by paragraph (3) or (4) of this AD, as applicable, it is not necessary that accomplishment of individual action is recorded for demonstration of AD compliance on a continued basis.

**Ref. Publications:**

Airbus A380 ALS Part 2 Revision 08 dated 28 May 2019.

The use of later approved revisions or variations of the above-mentioned document is acceptable for compliance with the requirements of this AD.

**Remarks:**

1. If requested and appropriately substantiated, EASA can approve Alternative Methods of Compliance for this AD.
2. This AD was posted on 25 July 2019 as PAD 19-140 for consultation until 22 August 2019. No comments were received during the consultation period.
3. Enquiries regarding this AD should be referred to the EASA Programming and Continued Airworthiness Information Section, Certification Directorate. E-mail: [ADs@easa.europa.eu](mailto:ADs@easa.europa.eu).
4. Information about any failures, malfunctions, defects or other occurrences, which may be similar to the unsafe condition addressed by this AD, and which may occur, or have occurred on a product, part or appliance not affected by this AD, can be reported to the [EU aviation safety reporting system](#).
5. For any question concerning the technical content of the requirements in this AD, please contact: Airbus – EIANA (Airworthiness Office), Telephone: +33 562 110 253, Fax: +33 562 110 307, E-mail: [account.airworth-A380@airbus.com](mailto:account.airworth-A380@airbus.com).

