

AIRWORTHINESS DIRECTIVE

released by DIRECTION GENERALE DE L'AVIATION CIVILE

Inspection and/or modifications described below are mandatory. No person may operate a product to which this Airworthiness Directive applies except in accordance with the requirements of this Airworthiness Directive.

Translation of 'Consigne de Navigabilité' ref. : 92-084-010(B) R2
In case of any difficulty, reference should be made to the French original issue.

A T R

ATR 72 airplanes

Fire detector

This Airworthiness Directive concerns ATR 72 airplanes series 100 and 200, equipped with PWC 124B engines on which SB PWC 21211 isn't embodied.

The following actions are made mandatory in order to make it possible to detect a fire in the inter-compressor case :

- Before January 1, 1993, install a fire detector on the inter-compressor case, following the instructions of SB PW 21111 and ATR 72-26-1004 and ATR 72-26-1005.

NOTE :

Any engine change requires redemonstrating compliance with this Airworthiness Directive.

REF. : SB PWC 21211
SB PWC 21111
SB ATR 72-26-1004
SB ATR 72-26-1005

The present Revision 2 replaces AD 92-084-010(B)R1 dated January 20, 1993.

EFFECTIVE DATE : APRIL 11, 1992
(same as the original AD)