

Lycoming Piston Engines

---

**AD/LYC/24    Increased Torque for Connecting Rod Bolt P/N 74644    11/91**

CANCELLED.

Background:    The torque limits for all connecting rod nuts are now detailed in Lycoming Publication SSP 1776 "Service Table of Limits".