

Fuel Supply and Metering Equipment

AD/FSM/14

**Marvel Schebler Carburettors - Drain
Plug - Inspection**

3/93

CANCELLED.

Background: With a once only compliance requirement of within 25 hours time in service, or before installation in an aircraft, after 12 January 1970, the requirements of this Directive have been adequately expressed.