COMMONWEALTH OF AUSTRALIA CIVIL AVIATION SAFETY AUTHORITY SCHEDULE OF AIRWORTHINESS DIRECTIVES

Fuel Supply and Metering Equipment

AD/FSM/26 Air Metering Stop Pin P/N 62-226 Fitted to 5/89 MA4-5, MA-5 and MA-6 Series Carburettors

Applicability: Facet Aerospace (Marvel Schebler) MA4-5, MA-5 and MA-6 series carburettors

manufactured after April 1984 whose part number and serial numbers are listed in the

Requirement Document.

Note: These carburettors may be used on but not limited to Lycoming 0-360, 0-540, VO-540 and TVO-435 series engines; Teledyne Continental 0-470 series engines and

Pezetel (Franklin) model 6A-350 series engines).

Requirement: Modify affected carburettors in accordance with Facet Aerospace products service

bulletin A1-88 dated August 1988.

Note: FAA AD 89-04-02 Amdt 39-6109 refers.

Compliance: Unless already accomplished prior to installation, at the next removal or prior to

achieving 200 operating hours after 18 May 1989 whichever is the sooner.

Background: This directive is issued to prevent a potential risk to the safety of flight due to the

possibility of the engine throttle becoming jammed inside the carburettor if the air

metering stop pin becomes loose.