

Propellers - Variable Pitch - Hartzell

AD/PHZL/38 “Y” Shank Blade - Inspection and Replacement 6/97

CANCELLED.

Background: The SB called up in this Directive has been incorporated in the applicable Hartzell Overhaul manuals.