
AIRWORTHINESS DIRECTIVE

For the reasons set out in the background section, the CASA delegate whose signature appears below revokes Airworthiness Directive (AD) AD/PHZL/48 Amdt 6

Propellers - Variable Pitch - Hartzell

**AD/PHZL/48
Amdt 6**

Propeller Blade Pilot Tube Bore

5/2002

Requirement: CANCELLED.

Background: The requirements of this AD were to check the blade pilot tube bore for cracks and assembly tooling marks, which could lead to cracking and blade separation. Due to Hartzell issuing SB 136 Revision H, which lists that requirements of this Directive are now incorporated into Hartzell Blade Overhaul Manual 133C, this Directive has been cancelled.



Eugene Paul Holzapfel
Delegate of the Civil Aviation Safety Authority

7 April 2002