
AIRWORTHINESS DIRECTIVE

For the reasons set out in the background section, the CASA delegate whose signature appears below revokes Airworthiness Directive (A.D) AD/PHZL/56 Amdt 4.

Propellers - Variable Pitch - Hartzell

**AD/PHZL/59
Amdt 4**

Two Blade "Y" Shank Aluminium Hub

5/2002

Requirement: CANCELLED.

Background: This Directive required an inspection of certain 2 blade "Y" shank hubs, reflecting FAA AD 90-02-23 and HC-SB-61-164C, which have been superseded by FAA AD 2001-23-08 and HC-SB-61-227R2 respectively. Due to the number and nature of these changes referred to in these documents, this Directive has been cancelled and AD/PHZL/74 has been issued to require compliance with Service Bulletin HC-SB-61-227 Revision 2.



Eugene Paul Holzapfel
Delegate of the Civil Aviation Safety Authority

4 April 2002