

Propellers - Variable Pitch - McCauley

---

**AD/PMC/28**

**Propeller Hub - Replacement**

**10/75**

- Applicability: Models D2AF34C52/80GF-0 and D2AF34C52A/ 80GF-0 with S/Nos. 63000 to 659999 which have not been modified in accordance with AD/PMC/20.
- Document: McCauley SB No. 111.
- Compliance: For propellers which have completed 1500 hours total time in service as at 28 November 1975 - within 100 hours time in service after 28 November 1975. For propellers with less than 1500 hours total time in service -before achieving 1600 hours total time in service.