COMMONWEALTH OF AUSTRALIA CIVIL AVIATION SAFETY AUTHORITY SCHEDULE OF AIRWORTHINESS DIRECTIVES

Propellers - Variable Pitch - McCauley

	AD/PMC/37	Blade Counterweight Bolt Replacement	5/83
--	-----------	--------------------------------------	------

Applicability: All 3AF32C504, 3AF32C505, 3AF32C506, 3AF32C507, 3AF32C508 and

3AF32C509 models with serial numbers 803546 through 816154.

Document: McCauley Service Bulletin 147.

Compliance: By the next maintenance release inspection, after 31st May 1983.

Background: The manufacturer reports failures of blade counterweight bolts. This Directive

introduces a new maintenance practise to nullify this problem.