

Propellers - Variable Pitch - Dowty Rotol

AD/PR/9 **Hub Driving Centre - Inspection** **NK**

Applicability: All model (c) R184/4-30-4/50 propellers not incorporating Mod. No. (c) VP 2486.

Document: Dowty Rotol SB No. 61-633.

Compliance: Before exceeding 2500 hours total time in service and thereafter at intervals not exceeding 750 hours time in service.