

Propellers - Variable Pitch - Dowty Rotol

AD/PR/20	Hub Front Face to Snout Radius - Inspection	NK
Applicability:	All model (c) R175/4-30-4/13E, (c) R186/4-30-4/16 and 16/1, (c) R212/4-30-4/22/1 propellers not modified in accordance with Mod. VP 2388.	
Requirement:	In accordance with an approved eddy current technique, inspect the hub front face to dome mount radius for cracking.	
Compliance:	For all propellers which have not been modified in accordance with Mod. VP 2388 - inspect in accordance with the requirement within 1500 hours time in service after 30 September 1978, and thereafter at intervals not exceeding 1500 hours.	
	<i>Note: NAC Eddy Current Technique TB-61-10 F3201 NAC9 is an approved technique.</i>	