

Propellers - Variable Pitch - Dowty Rotol

AD/PR/23	Feathering Springs - Operational Inspection	12/83
Applicability:	Propeller Aircraft R306/3-82-F/7 Gulfstream Aerospace Commander 690C, 690D, 695 and 695A R321/4-82-F/8 Fairchild Aircraft SA-227AC (Metro III) R321/4-82-F/9 Fairchild Aircraft SA-227AT (Merlin IVC) R324/4-82-F/9 Fairchild Aircraft SA-227TT (Merlin IIIC) R333/4-82-F/12 Jetstream 31 R334/4-82-F/13 CASA 212.	
Requirement:	Carry out a ground feathering check in accordance with Dowty Rotol Service bulletin 61-A995.	
Compliance:	(i) On fitment to the Aircraft prior to its first flight. (ii) For those propellers already installed, no later than 14 January 1984.	
Background:	In order to check that no undetected assembly failure exists, the manufacturer has deemed it necessary to carry out a once only feathering check.	