

Propellers - Variable Pitch - Dowty Roto1

---

**AD/PR/28**  
**Amdt 1**

**Hub Switches**

**10/89**

Applicability: Any Dowty Roto1 Propeller P/N R193/4-30-4/xxx with the following S/N installed on Fokker F-27 aircraft.

DRG 225/63, - 265/64, - 23/68, - 121/70, - 59/76, - 21/77, - 65/77, - 76/77, - 8/78, - 44/78, - 120/78, - 121/78, - 15/79, - 417/80 - 1127/80 - 3954/86.

Dowty Roto1 Propeller P/N R184/x-xx-x/xxx S/No DRG 118/65 installed on Gulfstream 1 G 159 aircraft.

Requirement: Inspect hub switches for correct fitment, location and correct brush installation within the hub switch block. Refer Dowty Roto1 Maintenance Manual 876 CM 61-2-4 Page 302/2.

*Note 1: Use switch P/N 601023026 in position 1 and 3 and switch P/N 601023027 in position 2.*

*Note 2: Netherlands AD 89-19 issue 2 refers.*

Compliance: Unless already accomplished at next inspection for issue of a Maintenance release or by 30 October 1989 whichever occurs first.

Background: Due to the possibility that the hub switches may have been incorrectly installed a one time inspection is required. Amendment 1 corrects a serial no. change.