

Propellers - Variable Pitch - Dowty Rotol

AD/PR/30

**Hub Mounting Face Dowel Inspection
Following Propeller Overtorque**

4/97

CANCELLED.

Requirements of this Directive are now contained in CAO 105 AD/F50/73 for the Fokker F50 series.