

Restraint Equipment

**AD/RES/7
Amdt 2**

**Safety Harness Buckles MS22013
and 44B26452 - Modification**

2/98

CANCELLED.

Background: This AD addresses possible inadvertent release of the buckle due to worn lever retention. Although issued in early 1970's, a recent investigation revealed that there has been no record of defects in Australia, USA or Canada of the subject buckles for any category of aircraft.