

Restraint Equipment

AD/RES/26 **AMI Industries Pilot Lap Belt Attachment Link** **7/93**

Applicability: Pilot and Co-Pilot Seats, Model 1108, serial numbers 004 through 189; as installed in, but not limited to, de Havilland Model DHC-8 series aircraft.

Requirement: Remove the lap belt attachment links and install the improved lap belt attachment link kit, P/N 1B9014-3R, in accordance with AMI Industries, Inc., Service Bulletin 25-1108-03.

Note: FAA AD 93-07-05 Amdt 39-8537 refers.

Compliance: Prior to 31 August 1993.

Background: The FAA received a report of a lap belt link fitting failure due to fatigue.