

Supplementary Equipment

AD/SUPP/4 **Air Equipment Rescue Hoist - Inspection
and Modification of Squib** **10/82**

Applicability: Air Equipment Rescue Hoists P/Nos. 76370, 76370-010, 76370-020 and 76375.

*Note: These hoists may be installed on (but not limited to) the following helicopters:-
Aerospatiale SA 341, SA 342, 3160, 316, 319, AS350, AS 355, SA 360C, SA 365C and
SA 365N.*

Requirement: 1. Inspect and modify hoists P/Nos. 76370, 76370-010 and 76370-020 in accordance
with Air Equipment Service Bulletin 25-62-0C Rev. 1 or later approved revisions.

 2. Inspect and modify hoist P/No. 76375 in accordance with Air Equipment Service
Bulletin 25-69-0B Rev. 1 or later approved revisions.

 3. For hoists not modified in accordance with paras. 1 and 2 provide a hand cable
cutter capable of ensuring a positive quick cable cut.

Compliance: For Paras. 1 and 2 - Before 1 October 1982.

 For Para. 3 - Before operation of the hoist.

Background: There have been several reported overseas defects which could cause the
pyrotechnical shearing device to become inoperative.