

Supplementary Equipment

AD/SUPP/10

Breeze-Eastern Hoists

11/88

Applicability: All Breeze-Eastern rescue hoists.

Requirement: Action in accordance with Breeze-Eastern Alert Advisory Bulletin No. CAB-100-30.

Compliance: In accordance with the Requirement Document.

Background: The manufacturer has determined that damage to a particular area of the load cable may evade detection during normal inspection, which could result in a serious compromise of cable integrity. This AD introduces regular inspections which are intended to significantly improve the operational safety of the rescue hoist system.