

**State of Israel
Ministry of Transport
Civil Aviation Authority**

**AD ISR I-35-2022-12-9
Date: Feb 8, 2023**

AIRWORTHINESS DIRECTIVE

This Airworthiness Directive, issued by the Civil Aviation Authority of Israel in accordance with the Israeli Air Navigation Regulations applies to an aircraft for which our records list you as the registered owner. It affects aviation safety and requires your immediate attention. No person may operate an aircraft to which an Airworthiness Directive applies, except in accordance with that Directive.

APPLIES TO: Aircraft serial numbers mentioned in SB 365-35-M058 for 737-300/-400 and SB 365-35-M011 for 737-700/-800 certificated in any category.

SUBJECT: **Supernumerary oxygen system mask replacement.**

REASON: Due to the lack of performance data available for oxygen mask P/N 28314-12 currently installed on aircraft, an oxygen mask with TSO C64a authorization is required to ensure compliance of each supernumerary oxygen mask & cylinder assembly with the airworthiness regulations.

ACTION: Supernumerary oxygen masks replacement. Oxygen masks P/N 28314-12 (Safran) by Oxygen masks P/N 174097-11 (B/E Aerospace) which are TSO C64a approved.

COMPLIANCE: Unless already accomplished, comply with this AD at the next suitable planned maintenance inspection within the next 12 months from the effective date of this AD

EFFECTIVE DATE: February 08, 2023.

FOR FURTHER INFORMATION CONTACT: Mr. Liran Cohen, Aircraft Certification Department, CAAI - P.O. Box 1101, 3 Golan Street, Airport City, Israel, 70151. Telephone: 972-3-9774529, E-mail: cohenli@mot.gov.il .