Beechcraft 400 Series Aeroplanes

AD/BEECH	400/4 Fuselage Rivets	13/93
Applicability:	Model 400A with serial numbers RK-1 through RK-41.	
	Model 400T with serial numbers TT-3 through TT-20.	
Requirement:	Action in accordance with Beechcraft Mandatory Service Bulletin 2482.	
	Note: FAA AD 93-16-12 Amdt 39-8670 refers.	
Compliance:	Within 100 hours time in service after 9 December 1993.	
Background:	The FAA received reports that during manufacture, rivets may have been inadvertently omitted from the area adjacent to the upper edge of the emerger door.	ncy exit