

Bombardier (Canadair) CL-600 (Challenger) Series Aeroplanes

AD/CL-600/3 Passenger Door Interior and Exterior Handles and Latch Mechanism - Inspection and Modification 3/83

Applicability: All models with S/Nos. 1024 to 1075.

Document: Canadair Challenger Alert SB No. A600-0203.

Compliance: Within 50 hours time in service after 31 March, 1983.

Background: Passenger door latch mechanisms and associated fittings have been found incorrectly rigged.